	Турс	e #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Er ro rs
1	BRS	L 4	3292	422/100.ccls. or 436/180.ccls. or (73/864.13,864.16,86 4.17).ccls.	USPA T; US-P GPUB; PO; JPO; DERW ENT	2004/06/1 5 23:08			0
2	BRS	L 5		(piezoelectric\$5 or piezo or magnet\$6 or thermal\$3 or pneumatic\$6) near10 (actuat\$4 or pulse\$2 or generat\$5 or element\$1 or driv\$3)	GPUB; EPO;	2004/06/1 5 23:14			0
3	BRS		2	plunger\$2 or rod\$1 or or syringe\$1 or barrel\$1)		2004/06/1 5 23:15			0
4	BRS	L 7	156	4 and 6		2004/06/1 5 23:15			)

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	D e	Er ro rs
5	BRS	L 8	93	7 and (wash\$3 or rins\$3)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/1 5 23:15			0
6	BRS	L 9	103	7 and (wash\$3 or rins\$3 or flush\$3)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2004/06/1 6 00:00		****	0
7		L 1 0	53	7 not 9	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/1 6 00:00			D